

Limited WARRANTY

Conveyor Service & Electric (CSE) manufactured products are to be free from defects with regard to workmanship and materials. All claims must be submitted to CSE in writing within a reasonable time from purchase. Defective goods claims will be investigated by CSE. The seller reserves the right to repair or replace all defective merchandise.

CSE will repair or replace at no cost (FOB) Santa Fe Springs, CA) any of its manufactured parts proving defective in materials or workmanship for a period of (1) one year or (2080) hours of equipment usage. Defects shall be verified by inspection as designated by CSE's, cost of removal and installation will be at purchaser's expense. CSE's liability is extended only to furnishing said part or parts.

CSE is not liable for consequential damages, such as loss of profits, delays or expenses incurred by failure of said part or parts. Failure due to abuse, incorrect adjustments, exposure to corrosive or abrasive environment or operation under damp conditions, does not constitute failure due to defects in materials or workmanship.

Component parts not of CSE's manufacture (i.e. motors, gear reducers, electrical, mechanical and/or pneumatic individual component parts) will be repaired or replaced at the option of the respective manufacturer/s. Please contact your sales representative, or manufacturer directly for all warranty claims.

NOTE: Motors, reducers, or electrical components tampered with before inspection shall be considered free of all warranty claims. Improper and/or incorrect installation and/or electrical wiring that results in damage to these items shall constitute voiding of the warranty. Only certified and/or properly trained persons should be performing mechanical and/or electrical installation of our equipment/products.

Conveyor Service & Electric (CSE)

9550 Ann Street

Santa Fe Springs, CA 90670-2616

Toll Free in US Phone#: 888-633-3996

Toll Free in US FAX #: 888-633-3990

Local Phone #: 562-777-1221

Local FAX #: 562-777-1220